498.00 mm


83.00 mm

110.00 mm

WIRELESS
2D BARCODE SCANNER
QUICK MANUAL


WS-3.1

Indicator Description



Indicator Type	State	Indicator Light
LED indicator	2.4G mode	Blue light
	Bluetooth mode	Green light
	Not paired	Green/blue light slow flash
	Pairing	Green/blue light quick flash
	Paired	Green/blue light on
	Charging	Red breath light flash
	Fully charged	Red light on

Indicator Description

Cradle	Dongle
	

Indicator Type	State	Indicator Light
LED indicator	Pairing	Green light flash
	Paired	Green light on

Manual Introduction

This is a quick user manual, if you need the full manual, please download it from our website or contact the seller.
* is the default setting.


Factory default

There could be an error setting if the scanner can not work, please try to set scanner to 'Factory default'.

Buzzer Description

1 medium sound and 1 high sound	Pairing success
1 medium sound	Scanning success
3 short sounds	Alarm prompt

2.4G Mode


*2.4G


2.4G receiver pairing

Note: Step 1: Scan '2.4G'; Step 2: Scan '2.4G receiver pairing'.

Bluetooth Mode


Bluetooth


Bluetooth HID pairing

Note: Step 1:Scan 'Bluetooth'; Step 2: Scan 'Bluetooth HID pairing'.

Version Information


Scanner version


Receiver version

Interface Type


*USB-HID


USB-VCOM(Driver is needed)

Data Upload Mode


Immediate mode*


Inventory mode

Data Processing In Inventory Mode


Clear all stored data


Check number of stored data


Upload all stored data

Sleep Time


Enter sleep immediately


Enter sleep after 1 min


Enter sleep after 5 min*


Enter sleep after 30 min

Language


English(USA)*


French


German


Turkish Q

Language


Portuguese(Brazil)


Italian


Spanish(Spain)


Universal language

*For more languages settings, please refer to the full manual.

Terminator


NONE


*CR


LF


TAB


CR/LF